
User Guide

RP10

DESCALING POWDER WITH COLOR CHANGE INDICATOR

Acid base powder suitable to remove scale in heating systems, heat exchangers, cooling circuits, pipes in stainless steel, aluminum, bras, tin, light alloys.

HOW TO USE

Dissolve the product in water at 10-15% about, (1kg of powder in 10 liters of water) and let circulate the solution inside the plant.

When the color changes, from red to yellow-orange, add some **REMOVER PLUS POWDER** until the red solution, there is no more effervescence.

ADVICES:

Once the descaling treatment is ended, wash the installation with a solution of **NEUTRALIZER** at 2-3 % then with running water.

RISK CLASSIFICATION

R 36 /38: Irritating to eyes and skin.

WARNINGS


S 2 : Keep out of the reach of children.

S 26 : In case of contact with eyes, immediately wash with plenty of water and ask for a doctor.

S 28 : In case of contact with skin, immediately wash with plenty of water and sodium bicarbonate.



Xi Irritant



Change log



Date of change	Change	Version
06-06-2019	Layout	003